MITSUBISHI MOTOR SALES OF AMERICA, Inc.

TECHNICAL SERVICE BULLETIN

SUBJECT:

NEW SERVICE GROUPS

NO. TSB-89-00-001

DATE June, 1989

MODEL All

As of June 1, the numbering of Technical Service Bulletin service groups has changed. TSBs published from June 1989 forward will conform to the new service group numbering shown below. The new Dealer Service Information Binder has tabs that correspond to the new service groups.
TSBs published January - May 1989 should be filed in the 1989 TSB Binder.
TSBs published June 1989 forward should be filed in the Dealer Service Information Binder.

NEW SERVICE GROUP		OLD SERVICE GROUP	
General	00	Intro & Troubleshooting	
Engine	11	Engine	09
Lubrication	12	Lub. & Maintenance	00
Fuel	13	Fuel System	14
Cooling	14	Cooling	07
Intake & Exhaust	15	Intake & Exhaust	11
Engine Electrical	16	Electrical	08
Emission Control	17	Emission Control	25
Clutch	21	Clutch	06
Manual Trans	22	Transmission	21
Automatic Trans	23	Transmission	21
Propeller Shaft	25	Prop Shaft & U-Joint	16
Front Axle	26	Transaxle	21
Rear Axle	27	Rear Axle	03
Wheels & Tires	31	Wheels and Tires	22
Power Plant Mount	32	Engine	09
Front Suspension	33A	Front Suspension	02
Active ECS	33B	Front or Rear Suspension	
Rear Suspension	34	Rear Suspension	17
Service Brakes	35	Brakes	05
Parking Brakes	36	Brakes	05
Steering	37	Steering	19
Body	42A	Body & Sheet Metal	23
Body Repair	42B	Body & Sheet Metal	23
Exterior	51	Body & Sheet Metal	23
Interior	52	Body & Sheet Metal	23
Chassis Electrical	54	Electrical	08
Htr, A/C, Ventilation	55	Heaters & A/C	24

Index # 027627

FILE UNDER: Group 00 General in the **Dealer Service Information** binder. (689)

CIRCULATE TO:
- ☐ GENERAL MANAGER
- ☐ PARTS MANAGER
- ☑ TECHNICIAN
- ☐ SERVICE ADVISOR
- ☑ SERVICE MANAGER
- ☐ WARRANTY PROCESSOR
- ☐ SALES MANAGER